




## ECS Configuration Change Request

Page 1 of

Page(s)

1. Originator Gary Gavigan	2. Log Date: 1/6/00	3. CCR #: 00-0018	4. Rev: -	5. Tel: X4113	6. Rm #: 2003F	7. Org. M&O
8. Title of Change: Transfer from EDF stockroom three ethernet hubs and one FDDI concentrator to be used at GSFC for M&O LAN.						
9. Originator Signature/Date  1/6/00		10. Class II	11. Type: CCR	12. Need Date: 1/14/00		
13. Office Manager Signature/Date  1/6/00		14. Category of Change: Update Baseline		15. Priority: (If "Emergency" fill in Block 28). Routine		
16. Documentation/Drawings Impacted: 840-TP-002-001 / GSFC DAAC & SMC M&O Equipment		17. Schedule Impact: N/A		18. CI(s) Affected: All		
19. Release Affected: N/A		20. Date due to Customer: 1/14/00		21. Impl. Date: 1/18/00		22. Estimated Cost: None
23. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input checked="" type="checkbox"/> GSFC <input type="checkbox"/> Other:						
24. Description of Change: (use additional Sheets if necessary) Transfer from Systems Engineering to M&O from the EDF stockroom, three ethernet hubs and one FDDI concentrator to be used at GSFC for M&O LAN. The requested hubs will be used to reconfigure the GDAAC M&O LAN so that the communication hardware would be relocated to the telephone/electrical closets closest to the persons cubicles. This would eliminate excess cables under the C101 computer room floor.						
25. Proposed Solution: (use additional sheets if necessary) Transfer from Systems Engineering to M&O from the EDF stockroom, three ethernet hubs and one FDDI concentrator to be used at GSFC for M&O LAN.						
26. Alternate Solution: (use additional sheets if necessary) NONE, without incurring costs to purchase already existing communication hardware to make this reconfiguration.						
27. Consequences if Change(s) are not approved: (use additional sheets if necessary) M&O LAN would need to purchase communication hardware to make this reconfiguration, as the GDAAC is short connections to the proposed staffing profile.						
28. Justification for Emergency (if Block 15 is "Emergency"):						
29. Site(s) Affected: <input type="checkbox"/> EDF <input type="checkbox"/> Mini-DAAC <input type="checkbox"/> VATC <input type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
30. Board Comments:				31. Work Assigned To:		
32. EDF/REL2 CCB Chair (Sign/Date):		33. Disposition: Approved A/C Disapproved Fwd/ECS Fwd/ESDIS		34. (TBD)		
35. M&O CCB Chair (Sign/Date):  11/2/00		36. Disposition: Approved A/C Disapproved Fwd/ECS Fwd/ESDIS		37. CM Manager's Closure:		
38. ECS CCB Chair (Sign/Date):		39. Disposition: Approved A/C Disapproved		40. CCR Closed Date:		

## ADDITIONAL SHEET

CCR #: 00-0018 Rev: — Originator: Gary Gavigan

Telephone: X4113 Office: M&O

**Title of Change:** Transfer from EDF stockroom three ethernet hubs and one FDDI concentrator to be used at GSFC for M&O LAN.

The EIN's for the hubs and concentrator are as follows:

EIN	Description
6957	24-Port Ethernet Hub
6746	24-Port Ethernet Hub
1344	12-Port Ethernet Hub
1306	FDDI concentrator

CM01A